




**City of Milpitas
Building and Safety Department**

Mailing Address: 455 East Calaveras Boulevard, Milpitas, California
95035-5479 – Tel. 408.586.3240, Fax 408.586.3285 www.ci.milpitas.ca.gov

**SPECIAL INSPECTION
REQUIREMENTS FOR PRE-CAST
WALL COLUMN FABRICATION**

Policy:	BDP-BLG07
Effective Date:	08/19/1992
Proposed by:	KI
Last Reviewed/ Revised:	05/10/17
Revised by:	JAC
Approved By: Gary King Acting Chief Building Official 	

WALL HEIGHT:	COLUMNS 6 FEET HIGH OR LESS	COLUMNS OVER 6 FEET HIGH
Reinforcing Placement		X
Concrete Placement		X
Cast Sample		X
Pick-up Sample		X
Compression Tests		X
Welding	X	X

NOTE:

- 1) Walls over 6 feet in height require special inspection for column fabrication.
- 2) Prior to erecting the panels, submit special inspection report to the City of Milpitas Building and Safety Department.